

Casting Processing, MH2252, 6hp



Lecture 7a+7b Precipitation of pores and slag inclusions at casting processes


Lect.7-1

Today's topics

- Repetition
 - Structure formation in cast materials
 - Microsegregation
 - Macrosegregation
- Precipitation of pores and slag inclusions at casting processes
 - Precipitation of pores
 - Gas reactions during casting
 - Pore morphology
 - Gases in steels and iron alloys/Aluminium
 - Slag inclusions
 - Cast iron


Lect.7-2

Characterisation of Dendrites - Dendrite Arm Distance and Growth Rate



Lect.5-3

Lamellar Eutectic Growth




$$v_{\text{growth}} \cdot \lambda^2 = \frac{dy_L}{dt} \cdot \lambda^2 = \text{const}$$


Lect.5-4

Macrostructure - Different Cooling Conditions


Casting method	Cooling Rate	Growth Rate	Columnar Zone	Macro-structure
Continuous casting	very strong	high	long	Figure 37 a
Ingot casting	strong	medium	short	Figure 37 b
Sand mould	weak	slow	absent	Figure 37 c



A: Strong cooling.
High casting temperature



B: Medium cooling.
Medium casting temperature




C: Weak cooling.
Low casting temperature.

Lect.6-5

The Lever Rule: Equilibrium Solidification

- High diffusion rates: *Lever rule* valid



$$x^L = \frac{x^S}{k} = \frac{x^0}{1 - f(1 - k)}$$

x^0 = initial concentration of the alloying element

f = fraction solid

k = partition coefficient (x^S/x^L) of the alloying element


$D^S > 10^{-10} \text{ m}^2/\text{sek}$

See chapter 7.3.2 The Lever rule


Lect.6-6

Scheil's Model

- $f < 0.9$ and low diffusion rate: *Scheil's model* valid
- There is an even composition in the melt at every moment
- The diffusion in the solid phase is neglectable
- There exists local equilibrium between solid and liquid phase can be described by the partition constant



$k = \frac{x^S}{x^L}$ the partition constant




$$x^L = \frac{x^S}{k} = x^0 \cdot (1 - f)^{-(1-k)}$$

$f = f_s = \text{fraction solid}$

See chapter 7.3.1 Scheil's Model for Microsegregation

Lect.6-7

Macroseggregations in Ingots



See chapter 11.9 Macroseggregations in Steel Ingots

Lect.7-8

Sedimentation Segregation - +/- Segregation



H



h



- a) Equiaxed crystals in the melt before sedimentation.
- b) Equiaxed crystals, including their associated melt, after sedimentation

Positive segregation (+): the concentration of the alloying element exceeds the average concentration.

Negative segregation: there is instead a lack of the alloying element (lower than average concentration)


Lect.7-9

A-segregations – Ghost lines!




- The density of the melt increases linearly with decreasing temperature.
- The density of the melt within the two-phase region **decreases** due to **microsegregation of lighter alloy elements**.
- Natural convection in the melt and an **opposite convection pattern** in the two-phase region.
- Higher concentration of alloy elements will lower the liquidus temperature and cause **re-melting of solid structure**.
- Ghost-lines!

A-segregations - Freckles



A = area of solidification front
 Vertical cut through a channel at the solidification front
 N = number of A-segregation channels per m




Channels (ghost lines/freckles) in castings are caused by natural convection due to concentration gradients in the two-phase region during the solidification process of an ingot.

The channels are created in the partly solidified two-phase region S+L.

Lect.7-11

V-segregation

- Vacuum, caused by the solidification shrinkage in the lower parts of the ingot.
- Cannot be filled by melt from above because the distance is long and the resistance from the dendrite arms is great.
- The pressure difference, which arises between the different parts of the ingot results in a general settling of the crystals in the middle zone.




Lect.7-12

Porosity in castings

- Deteriorate quality of a casting
- Lower mechanical properties
 - Reduced elasticity
 - Decreased impact resistance
- Risk for crack formation
- Reduced surface quality during machining
- Gas Porosity
 - Gas entrapped during casting
 - Precipitation of dissolved gas
 - Smooth surface of porosity
- Shrinkage Porosity
 - Solidification shrinkage
 - Uneven surface of porosity

Lect.7-13



Shrinkage porosity - gas porosity



- Pores and porosity (micro / macro) cause surface defects and poor mechanical properties.
- Shrinkage porosity, arises because insufficient feeding of melt to the last solidified areas.
- Gas porosity, resulting from a high content of gas-forming substances in the melt.


Sources for Common Gases in Metals

- Entrapped Air
- From atmosphere
 - Oxygen, Nitrogen
 - Hydrogen from moisture
 $\text{H}_2\text{O} + \text{M} = 2\text{H} + \text{MO}$ and $2\text{H} = \text{H}_2(\text{g})$
- In Steels and Iron
 - Carbon monoxide, $\text{C} + \text{O}_2 = 2\text{CO}(\text{g})$
- Reaction with mould materials
 - H_2 (moisture in sand), O_2 , CO , CO_2 , SO_2



Lect.8-15

Condition for pore precipitation (Pressure in a Gas Bubble)



$$p_{gas} = p_{atm} + p_h + \frac{2\sigma}{r}$$

$$p_{gas} > p_{atm}$$


Condition for pore precipitation (simplified)

Note: the lower surface tension – the easier it is to form bubbles (gas pores)

See chapter 9.3.1 Gas Reactions and Gas Precipitation in Metal Melts

Lect.7-16

Gas Solubility in Metal Melts




The concentration of the dissolved gas atoms in the melt or in the solid phase is proportional to the square root of the partial pressure of the gas in the surrounding atmosphere

See chapter 9.7.1 Hydrogen in Steel and Iron Alloys

Lect.7-17


Gas Solubility and the Phase diagram



Region 1: Gas content totally dissolved in solid.
Region 2: Precipitation of gas porosity during solidification
Region 3: Precipitation of gas porosity during melt cooling followed by gas porosity during solidification

Lect.7-18

The Lever Rule



Lect.7-19

Pore precipitation in solidifying melts

- $x^L = \left(\frac{x^S}{k}\right) = \frac{x^0}{1 - f(1 - k)}$

The Lever Rule.
 - Always valid for gaseous elements
 - f^S in relation to x^L
- $[G] = \text{const} \sqrt{p_{G_2}}$


Sievert's Law
 - Valid for two atomic gas molecules
 - x^L in relation to P_{G_2}
- $p_{\text{gas}} > p_{\text{atm}}$

Condition for pore precipitation
 - Simplified, close to the melt surface
 - P_{G_2} in relation to P_{atm}
- $k = \frac{x^S}{x^L}$

The partition coefficient
 - close to 1, low enrichment, $\ll 1$ large enrichment to the liquid

Lect.8-20

Rounded Pores (Region 3)






Precipitated in melt
 Composition in melt $x^0 > x^L$

Lect.7-21


Elongated Pores (Region 2)

- Nucleated in the two phase region - between the dendrites
- Formed when the initial gas composition not is initially saturated
 $x^S < x^0 < x^L$



Lect.7-22


Different types of pore structures



Lect.7-23

Methods of lowering the dissolved gas content in metal melts

- Solidification – re-melting
- Stirring
 - Subsonic stirring
- Lowering the partial pressure
 - Vacuum treatment
 - Inert gas bubbling
 - Active gas bubbling
- Desoxidation - precipitation of secondary phases



Rotating Impeller

Common gases

H_2 : Hydrogen



N_2 : Nitrogen

O_2 : Oxygen

CO : Carbon monoxid

Lect.7-24

Hydrogen Pick-Up in Aluminium




Lect.7-25

Degassing of Aluminium Melts



Porous Plug


- Inert gas (Nitrogen or Argon)
- Reactive gases (Chlorine)



Lect.7-26


Gases in Steels and Iron

- Carbon monoxide
 - $\text{C} + \text{O} = \text{CO (g)}$
- Oxygen
 - From oxygen in atmosphere
 - Remove by addition of desoxidant
 - $\text{M} + \text{O} = \text{MO}$
 - Al, Si, Mg
- Hydrogen
 - $2\text{H}_2\text{O} = 2\text{H}_2 + \text{O}_2$
 - $\text{C} + \text{O}_2 = \text{CO} + \text{H}_2$
 - $\text{H}_2 = 2\text{H}$
 - Avoid moisture, bubble with inert gas



Lect.7-27

Hydrogen concentration in a steel melt



- Hydrogen pick up
 $2\text{H}_2\text{O} = 2\text{H}_2 + \text{O}_2$
 $[\text{H}]^2 [\text{O}] = \text{const}$

Note: a decrease of the oxygen concentration leads to an increased hydrogen concentration as a consequence of the solubility product of water

Lect.7-28

Oxygen and Carbon Monoxide in a Steel melt


$$c_{\text{C}}^{\text{L}} \cdot c_{\text{O}}^{\text{L}} = 0.0019 \cdot p_{\text{CO}} \quad (\text{w/o and atm})$$

$$y_{\text{O}} = c_{\text{O}}^{\text{L}} / c_{\text{O}}^{\circ} = \frac{1}{1 - f \cdot (1 - 0.054)}$$

$$y_{\text{C}} = c_{\text{C}}^{\text{L}} / c_{\text{C}}^{\circ} = \frac{1}{1 - f \cdot (1 - 0.020)}$$

$$y_{\text{CO}} = y_{\text{C}} \cdot y_{\text{O}} = \frac{c_{\text{C}}^{\text{L}} \cdot c_{\text{O}}^{\text{L}}}{c_{\text{C}}^{\circ} \cdot c_{\text{O}}^{\circ}}$$

Both C and O are present in all steel and iron melts. When the steel solidifies both C and O concentrate in the melt and the saturation limit may be exceeded




See chapter 9.7.3 Oxygen and Carbon Monoxide in Steel and Iron Alloys

Lect.7-29


Slag Inclusions (Cinders)

- Slag:
 - Non-Metallic Inclusions in Metals
- Microslags:
 - Not detectable by naked eye (<0.1 mm)
 - Most often formed interdendritic during solidification
 - $\text{M} + \text{O} = \text{MO}$ where M = desoxidation element (Si, Al etc.) Solubility Product $[\text{M}][\text{O}] = K_{\text{MO}}$
- Macroslags:
 - Visible by eye (>0.1 mm)
 - Formed in the melt before solidification
 - Reaction products from desoxidation elements
 - Refractory material from mould walls




Lect.8-30

Cast Iron - Fe-C alloys with carbon content > 2.1 w/o C



- Steel < 2% C
- Cast Iron > 2% C (2.5-4.3 %C)
- T_E = Stable (1153 °C)
- T_E = Metastable (1147 °C)



Promotes Grey Iron

- Si - Important
- Ni, Cu, Co
- Slow Cooling Rate
- Inoculation

Promotes White Iron

- Cr, V, Ti
- High Cooling Rate

Lect 6-31


White Cast Iron



- Mixture of cementite and austenite
- Eutectic is called ledeburite
- Very hard
- Very low ductility = fragile
- High wear resistance
- Friction material

Lect 5-32

Different types of grey cast iron



I, II : Flake graphite


III : Compacted graphite, CGI

IV, V : Vermicular graphite

VI : Nodular graphite

Lect 5-33


A. Flake Graphite



- Spherical cells
- Very good castability
- Good damping properties

Lect.5-34


B. Nodular Graphite (Ductile Iron)



- Spheroidal graphite morphology
- By adding Cr or Mg
- More difficult to cast
- Good ductility
- High strength

Lect.5-35

C. Compact Graphite Iron (CGI)



- Intermediate between flake and spheroidal graphite - with respect to structure, castability and strength
- By adding small amounts of Cr or Mg
- Difficult to control microstructure

Lect.5-36

**Recommended reading in
“Materials Processing during Casting”, by
Hasse Fredriksson and Ulla Åkerlind**

Chapter:

□ 9.1 – 9.9

Lect.7-37
